

UD28	s=0,6mm		CD60	s=0,6mm		CD48	s=0,6mm		CW50	s=0,6mm	
CW75	s=0,6mm		CW100	s=0,6mm		UW50	s=0,6mm		UW75	s=0,6mm	
UW100	s=0,6mm		UC5035	s=0,55mm		L2323	s=0,25mm		L2313	s=0,25mm	
U-30x27,5	s=1,5mm		U-30x25	s=1,5mm		U-33x25	s=1,5mm		U-19x38	s=1,5mm	
U-35x45/48	s=2mm		U-38x47	s=2mm		U-38x45	s=2mm		U-36x50	s=2mm	
U-38x45	s=1,2mm		U-19x37	s=1,2mm		U-25,5x30	s=1,2mm		U-21x32,5	s=1,2mm	
U-26x40	s=1,2mm		U-28x26,5	s=1,2mm		U-28x28	s=1,2mm		U-29x26	s=1,5mm	
U-29,5x47,5	s=1,5mm		U-30x22	s=1,2mm		U-30x26	s=1,2mm s=1,5mm		U-30x28,5	s=2mm	
U-30x7/28	s=1,2mm		U-31x28	s=1,5mm		U-32x15/22	s=1,5mm		U-32x27	s=1,5mm	
U-32,5x40	s=2mm		U-30x30	s=1,2mm s=1,5mm		U-30x25	s=1,5mm		U-32x14/30	s=2mm	
U-59x31	s=1,2mm		U-50x30	s=2mm		U-32,5x42	s=1,2mm		U-32,5x40	s=2mm	
U-33x50	s=1,5mm		U-30x21	s=1,2mm s=1,5mm		U-34x27	s=1,2mm		U-35x28	s=1,2mm	
U-35x50	s=1,8mm		U-36x44,5	s=1,5mm		U-38x16/25	s=1,5mm		U-40x13/22	s=1,2mm	
U-36x12/27	s=1,2mm		U-36x18/26	s=1,5mm		U-40x15/28	s=1,2mm s=1,5mm		U-35x32	s=1,2mm	

**Special Machines for Special Needs**